

# Oil Field Environmental Incident Summary

**Incident:** 20151231154535      **Date/Time of Notice:** 12/31/2015 15:45

**Responsible Party:** Oasis Petroleum

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** WADE FEDERAL 5300 30-29 CTB 1

**Field Name:** BAKER

**Well File #:**

**Date Incident:** 12/30/2015      **Time Incident:** 04:30

**Facility ID Number:** 228394-01

**County:** MCKENZIE

**Twp:** 153

**Rng:** 100

**Sec:** 30

**Qtr:** NE SW

**Location Description:** North west corner of facility , west of flare stacks

**Submitted By:** Todd Hanson

**Received By:**

**Contact Person:** Dustin Anderson  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No risk, oil and snow have been cleaned up

**Areal Extent:**

Approximately 50' wide and 150' long

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Pumper needs to stay around the battery when pumps are started to make sure all equipment is operating properly

**Wastes Disposal Location:** All snow and oil have been piled into the flare pit

**Agencies Involved:**

**Updates**

---

**Date:** 12/31/2015 **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted areas off location. Followup is required.

---

**Date:** 1/4/2016 **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site 2:35 p.m. The weather was sunny, 25°F, with wind calm. I talked to company rep. He indicated that the area had been scraped up, and they had removed a lot of snow. There was snow piled up on the pad near the flare. The area directly east of the flare was bare of snow. There is also a new pipeline right of way that had no vegetation growing on it, and it was also bare following the east edge of the pad. The area is pasture; the sprayed area had been scraped down leaving only the root balls of the pasture plants. The area was cleaned up to a ravine located east of the pad. I could not see any oil staining on the soil or areas outside of spray area. It appears the soil has been blowing from the exposed areas to the east of the bare areas. More followup needed next growing season. 48.0422412, - 103.602645

---

**Date:** 5/20/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 14:30, 5/20/2016.

No sign of impacts at the time of inspection.

No on-site inspection necessary.

---

**Date:** 5/23/2016    **Status:** Awaiting Documentation

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Contact responsible party for follow-up report with any sample results.

Awaiting documentation.

---

**Date:** 11/3/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 4:16 11/3/2016.

Impacted area has sporadic vegetation growing throughout. Contact company to ensure proper reseeded.

More follow-up is necessary.